



IECEX Facility Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

FAR Ref. No.: **NL/DEK/FAR11.0002/14**

Page 1 of 1

Issuing ExCB: **DEK - DEKRA Certification B.V.**

Date of issue: **:2025-05-12**

Status :**Issued**

Audit date:

2025-05-12

Valid Until:

2027-05-27

Location(s) audited:

Bakker Repair B.V.
Ringersstraat 2
3364 BA Sliedrecht
Netherlands

Service Facility:

Bakker Repair B.V.
Ringersstraat 2
3364 BA Sliedrecht
The Netherlands
Netherlands

Details of change: **1st surveillance**

Type of work Covered **Repair and overhaul of Ex d, Ex e, Ex p, Ex n and Ex t motors, transformers, generators and fans.**
by Service Facility:

Related FARs:

NL/DEK/FAR11.0002/00
NL/DEK/FAR11.0002/03
NL/DEK/FAR11.0002/06
NL/DEK/FAR11.0002/09
NL/DEK/FAR11.0002/12

NL/DEK/FAR11.0002/01
NL/DEK/FAR11.0002/04
NL/DEK/FAR11.0002/07
NL/DEK/FAR11.0002/10
NL/DEK/FAR11.0002/13

NL/DEK/FAR11.0002/02
NL/DEK/FAR11.0002/05
NL/DEK/FAR11.0002/08
NL/DEK/FAR11.0002/11

Related IECEx Service
Facility Certificates:

Comments: