



Linde Gas

Rewinding 16,5 MW motor - 2018

- ✓ Inspection
- ✓ Transport
- ✓ Repair
- ✓ Commissioning

Bakker Repair + Services managed to repair a 16,5 MW motor from Linde Gas within a record time of three weeks. We came to the rescue when Linde Gas's own supplier needed more than six weeks to deliver the defected part.

The 16.5-megawatt electric motor is essential to Linde Gas for the production of nitrogen for natural gas at its production site in IJmuiden. Since the motor failed, an old motor with less capacity had to take over, but this situation could not last too long. When Linde Gas's own Original Equipment Manufacturer (OEM) indicated he needed six weeks or more to supply the vital coil of the rotor, the company called its maintenance and repair partner Bakker Repair + Services. Bakker duplicated the part and repaired the motor in half the lead time, thus helping out Linde Gas.

The 35-tonne giant motor was dismantled at the production site in IJmuiden and transported with special road transport to Sliedrecht. There, the new part was built in and the motor was repaired. Due to the urgency of the repair, Linde Gas used Bakker's 24/7 service. That company worked seven days a week, 20 hours a day, to complete the project. Within three weeks, the repaired motor was transported back to Linde Gas IJmuiden and reinstalled on site.



Wilt u meer weten?

Bel: +31(0)184 41 05 55

Mail: info@bakker-repair n